

# EE-362 ELECTROMECHANICAL ENERGY CONVERSION-II

## Starting Methods and Operating Modes of Induction Machines

Ozan Keysan

[keysan.me](http://keysan.me)


Office: C-113 • Tel: 210 7586

# Induction Motors




20 MW Induction Motor for [HMS Queen Elizabeth](#)

# Induction Motors




Power and Propulsion Single Line Diagram



## Single Line Diagram of HMS Queen Elizabeth Power System

# Typical Torque Curve of an Induction Motor




Speed-Torque Curve for a Three-Phase Induction Motor

## Torque Graphs



# What is wrong with directly connecting motor to a constant voltage supply (i.e. grid)?

- High Start-up Current ✓
- Low(or high) Torque at Start-up ✓



# Starting Methods (Source Side):

## 1- Use Auto-transformer (Variac)



$$P_{rech} \propto I_2^2 \cdot \frac{(1-s)}{s} R_2'$$





$$\underline{\underline{T \propto V^2}}$$

Apply a smaller voltage during start-up, and increase it gradually.

Remember: Torque  $\propto V^2$

# Starting Methods (Source Side):


## 2- Use (Y - Δ) switch



	Normal operation (Δ)	Y connection (During Startup)
Phase Voltage	$V_{ell}$	$V_{ell}/\sqrt{3}$
Phase Current	$I_{\Delta}$	$I_{\Delta}/\sqrt{3}$
Starting Torque	$T_{\Delta}$	$T_{\Delta}/3$

# Starting Methods (Source Side):

## 3- Soft Starters




[Soft Starters](#), [Soft starter vs Motor Drive](#)



# Starting Methods (Source Side):

## 4- Induction Motor Drives


### Variable Voltage-Frequency Source (or Variable Frequency Drives)





# Starting Methods (Source Side):

## 4- Induction Motor Drives

### Variable Voltage-Frequency Source (or Variable Frequency Drives)




# Starting Methods Comparison:



# Starting Methods (Machine Side):

How to increase the starting torque, but reduce the starting current at the same time?


$$s_{maxT} = \frac{\overset{\uparrow}{r'_2}}{\sqrt{R_1^2 + (X_1 + X'_2)^2}}$$



$$T_{max} = 3 \frac{0.5V^2}{\omega_s \left( R_1 + \sqrt{R_1^2 + (X_1 + X'_2)^2} \right)}$$


# Starting Methods (Machine Side):

Increase rotor resistance ( $r'_2$ )




# Starting Methods (Machine Side):

Increase rotor resistance ( $r'_2$ )




# How to modify ( $r'_2$ )?

1 - Add External Resistor: Easy for wound rotor induction motors by using external resistance



# How to modify ( $r'_2$ ) for squirrel cage motors?

2 - Use Deep Rotor Bars: Utilize rotor resistance change with skin effect



$$N_r = 0$$

$$f_s = 50\text{Hz}$$

Rotor bar currents  $\Rightarrow$  50Hz current

$$N_r = 900\text{rpm}$$

$$N_s = 1000\text{rpm}$$

$$s = 0,1$$

$$f_s = 50\text{Hz}$$



Rotor bar currents  $\Rightarrow$  5Hz



# How to modify ( $r'_2$ ) for squirrel cage motors?

2 - Use Deep Rotor Bars: Utilize rotor resistance change with skin effect

# Rotor Bar Shapes




For curious students: [Rotor design](#), [Motor design classes](#)

# Complete Torque Characteristics

Can slip be larger than 1, or can it be less than 0?

$$P = T \cdot \omega$$



# Operation Modes of Induction Motors

1- Motoring


2- Generating

3- Braking

# Motoring

Power Flow: Electrical to Mechanical

Slip:  $0 < s < 1$     $0 < N_r < N_s$




# Generating

## Power Flow: Mechanical to Electrical

Slip:  $s < 0$

$$N_r > N_s \quad P = T\omega$$



# Braking (Plugging)


Power Flow: Mechanical+Electrical to Heat

Slip:  $s > 1$

$$N_r < 0$$

$$P = T \cdot \omega$$


(+) (-)



# Machine Dynamics

## Torque Balance Equation

$$\underline{T_{elec}} - \underline{T_{load}} - T_{friction} = J \frac{d\omega}{dt}$$



$$0 = J \frac{d\omega}{dt}$$

$\frac{d\omega}{dt} = 0 \Rightarrow$  Speed is constant



# Four-Quadrant Operation

