EE-464 STATIC POWER CONVERSION-II

Other PWM Techniques

Ozan Keysan

<u>keysan.me</u>

Office: C-113 • Tel: 210 7586

You already implemented in the first semester



Figure 2.2. Buck Converter with Hysteretic Current-Mode Control: A control sig-

If your current is higher than your reference, reduce the current (switch off), if not increase the current (Switch ON)



For an inverter, just change your reference current to a sinusoidal waveform instead of a constant reference.



. The switching frequency is varying

- . The switching frequency is varying
- . Difficult to design filter (because of varying fs)

- . The switching frequency is varying
- . Difficult to design filter (because of varying fs)
- . Can induce side-band harmonics

- . The switching frequency is varying
- . Difficult to design filter (because of varying fs)
- . Can induce side-band harmonics
- . Simple control and implementation





Field Oriented Control (FOC) in Electrical Machines



- What is FOC?
- Field oriented Control of PM Motors

How to aim to a moving target?

How to aim to a moving target?



Some Useful Mathematical Tools

Some Useful Mathematical Tools

- . Clarke Transformation
- . Park Transformation

<u>Clarke</u> Transformation

(a-b-c) to lphaeta Transformation

From three-phase to two orthogonal phase transformation

<u>Clarke</u> Transformation

(a-b-c) to lphaeta Transformation

From three-phase to two orthogonal phase transformation

Main Idea: In a balanced three-phase system, $I_a + I_b + I_c = 0$ so there is redundant information and system can be reduced to two variables.

How do you define the resultant (black) phasor?



11/68

Clarke Transformation



Clarke Transformation

$$i_{lphaeta}(t) = rac{2}{3} egin{bmatrix} 1 & -rac{1}{2} & -rac{1}{2} \ 0 & rac{\sqrt{3}}{2} & -rac{\sqrt{3}}{2} \end{bmatrix} egin{bmatrix} i_a(t) \ i_b(t) \ i_c(t) \end{bmatrix}$$

Park Transformation in Space



i.e. Interstellar - Docking Scene

From stationary frame to rotationary frame

From stationary frame to rotationary frame

Instead of dealing with sinusoidal signals, just use the magnitudes.

From stationary frame to rotationary frame

Instead of dealing with sinusoidal signals, just use the magnitudes.

When reconstructing signals use the rotor position information





17 / 68



$I_d = I_lpha cos(heta) + I_eta sin(heta)$



$$egin{aligned} &I_d = I_lpha cos(heta) + I_eta sin(heta) \ &I_q = I_eta cos(heta) - I_lpha sin(heta) \end{aligned}$$



$$egin{aligned} &I_d = I_lpha cos(heta) + I_eta sin(heta) \ &I_q = I_eta cos(heta) - I_lpha sin(heta) \end{aligned}$$

Reference Frames



Clarke and Park Transformations



Torque and Flux Control

- Id: Proportional to flux in the air-gap
- Iq: Proportional to torque generated

Inverse Transforms
Inverse Transforms

Required to apply reference voltage and current waveforms (sinusoidals)

Inverse Transforms

Required to apply reference voltage and current waveforms (sinusoidals)

- . Inverse Park Transform
- . Inverse Clarke Transform

From rotation frame to stationary frame

From rotation frame to stationary frame

$$I_{lpha} = I_d cos(heta) - I_q sin(heta)$$

From rotation frame to stationary frame

$$egin{aligned} &I_lpha &= I_d cos(heta) - I_q sin(heta) \ &I_eta &= I_q cos(heta) + I_d sin(heta) \end{aligned}$$

From two-axis orthogonal plane to 3-phase stationary frame.



Whole Workflow



Classical Vector Control Diagram



25 / 68

Vector Control in PMSM



Vector Control in Induction Motors



Summary



Further Reading

Vector Control for Dummies

- What is Field Oriented Control?
- **Field Oriented Control**
- Field Oriented Control of AC Motors
- Sensorless PMSM Field Oriented Control
- Space Vector PWM



Anti-parallel diodes are not shown.



Each leg has two positions:



Each leg has two positions: top switch closed (1)



Each leg has two positions:



Each leg has two positions: bottom switch closed (0)







- 000 v_0 (zero vector)
- 001 v_1 (Phase +U)
- 010 v_2 (Phase +V)
- 011 v_3 (Phase -W)
- 100 v_4 (Phase +W)
- 101 v_5 (Phase -V)
- 110 v_6 (Phase -U)
- 111 v_7 (zero vector)



35 / 68









39 / 68





41 / 68



42 / 68

Square Wave Operation



BLDC Drive with square wave







46 / 68

Voltage Synthesizing



47 / 68
Voltage Synthesizing







Switching Sequence: 000-001-011-111

Switching Sequence:

. Zero Vector (000)

Switching Sequence:

- . Zero Vector (000)
- . Basic Vector (i.e. 001)

Switching Sequence:

- . Zero Vector (000)
- . Basic Vector (i.e. 001)
- . Basic Vector (i.e. 011)

Switching Sequence:

- . Zero Vector (000)
- . Basic Vector (i.e. 001)
- . Basic Vector (i.e. 011)
- . Zero Vector (i.e. 111)

Switching Sequence:

- . Zero Vector (000)
- . Basic Vector (i.e. 001)
- . Basic Vector (i.e. 011)
- . Zero Vector (i.e. 111)

Only one switch position is changed at each step!





Phase Voltages

• Space Vector PWM generates less harmonic distortion

- Space Vector PWM generates less harmonic distortion
- . Space Vector PWM utilizes input voltage more 1/2 vs $1/\sqrt{3}$ (15% more)



55 / 68



$$\hat{V}_{p-n} = rac{V_{DC}}{2}$$

The inverter is connected to 400 V_{l-l} grid with a 3-ph diode rectifier:



The inverter is connected to 400 V_{l-l} grid with a 3-ph diode rectifier:



 $V_{DC} =$

The inverter is connected to 400 V_{l-l} grid with a 3-ph diode rectifier:



$$V_{DC}=rac{3\sqrt{2}}{\pi}V_{l-l}$$
 .

The inverter is connected to 400 V_{l-l} grid with a 3-ph diode rectifier:



$$V_{DC}= rac{3\sqrt{2}}{\pi} V_{l-l} = 1.35 V_{l-l} = 540 V$$





Maximum motor phase voltage:



Maximum motor phase voltage:

$$V_{phase-rms} = rac{V_{DC}}{2\sqrt{2}} = 190V$$

which is quite low for standard motors!

How can you increase the output voltage beyond the DC-link voltage limit?

How can you increase the output voltage beyond the DC-link voltage limit?



A sinusoidal reference voltage output:





Assume you apply a waveform like that:

which composes of the fundamental and a third-harmonic component

Such that $V=rac{V_{DC}}{2}$ at $\pi/3$



61/68

What is the phase voltage?



Third harmonic cancels itself (common-mode voltage), the potential of the neutral votlage is oscillating, but the winding doesn't see this change and observe a pure sinusoidal.

What is the phase voltage?

THIPWM:
$$V_{phase-rms} = rac{V_{DC}}{\sqrt{6}} = 220V$$

What is the phase voltage?

THIPWM:
$$V_{phase-rms} = rac{V_{DC}}{\sqrt{6}} = 220 V$$

%15 higher than SPWM

$$(V_{phase-rms}=rac{V_{DC}}{2\sqrt{2}}=190V)$$


What is the phase voltage for one of the SVPWM vectors?

What is the phase voltage for one of the SVPWM vectors?

$$\hat{V_n}=rac{2}{3}V_{DC}$$

What is the phase voltage for one of the SVPWM vectors?

$$\hat{V_n}=rac{2}{3}V_{DC}$$

What if two adjacent vectors are applied for %50, %50?

What is the phase voltage for one of the SVPWM vectors?

$$\hat{V_n}=rac{2}{3}V_{DC}$$

What if two adjacent vectors are applied for %50, %50?

$$=rac{2}{3}V_{DC}rac{\sqrt{3}}{2}=rac{1}{\sqrt{3}}V_{DC}$$

Same with THIPWM:
$$V_{ph,rms} = rac{1}{\sqrt{6}} V_{DC} = 220 V$$

Magnitude comparison of SPWM and SVPWM



Space Vector (SVPWM)

Max.
$$V_{l-l,rms} = \sqrt{3} rac{V_{dc}}{\sqrt{3}} rac{\sqrt{3}}{\sqrt{2}}$$

Space Vector (SVPWM)

Max.
$$V_{l-l,rms}=\sqrt{3}rac{V_{dc}}{\sqrt{2}}=rac{V_{dc}}{\sqrt{2}}=0.707V_{dc}$$

Space Vector (SVPWM)

Max.
$$V_{l-l,rms}=\sqrt{3}rac{V_{dc}}{\sqrt{2}}=rac{V_{dc}}{\sqrt{2}}=0.707V_{dc}$$

Sinusoidal (SPWM)

Space Vector (SVPWM)

Max.
$$V_{l-l,rms}=\sqrt{3}rac{V_{dc}}{\sqrt{2}}=rac{V_{dc}}{\sqrt{2}}=0.707V_{dc}$$

Sinusoidal (SPWM)

Max.
$$V_{l-l,rms} = \sqrt{3}rac{rac{V_{dc}}{2}}{\sqrt{2}}$$

Space Vector (SVPWM)

Max.
$$V_{l-l,rms}=\sqrt{3}rac{rac{V_{dc}}{\sqrt{3}}}{\sqrt{2}}=rac{V_{dc}}{\sqrt{2}}=0.707V_{dc}$$

Sinusoidal (SPWM)

Max.

$$V_{l-l,rms} = \sqrt{3}rac{rac{V_{dc}}{2}}{\sqrt{2}} = rac{\sqrt{3}V_{dc}}{2\sqrt{2}} = 0.612V_{dc}$$

SVPWM is %15 higher than SPWM

You can download this presentation from: <u>keysan.me/ee464</u>