EE314 Semester Schedule (2015)

WEEKS	EXPERIMENT #
W4: 9-15 March	1
W5: 16-22 March	2
W6: 23-29 March	X-Basic and Standard TTL Inverters
W7: 30 March- 5 April	3
W8: 6 -12 April	4
W9: 13-19 April	5
W10: 20-26 April	6 (No lab for THA on 23 April. THA will
	perform EXP6 next week (23 April→30
	April))
W11: 27 April – 3 May	7 (THA performing EXP6, No lab for FA on
	1 May)
W12: 4-10 May	8 (ALL performing EXP8) THA performing
	EXP7 on Saturday morning (9 May), FA
	performing EXP7 on Saturday afternoon
	(9May)).
W13: 11-17 May	Lab Finals
W14: 18-24 May	Project Work (No lab for TM and TA (19
	May)(To be compensated later)
25-31 May	Project Work (OLSA v2 Assignment for 25
	May – 7 June)
1 -7 June	Project Demo (ALL ends at 5 June 17:00)